



Memorandum

*To: Diane Salkie, EPA Region 2
Elizabeth Franklin, USACE*

*From: Yeqing Liu, CDM Smith
Keegan L. Roberts, Ph.D., PE, CDM Smith*

Date: September 28, 2018

*Subject: Summary of Oversight of Cap Inspection at River Mile 10.9
September 10–11, 2018
Lower Passaic River Restoration Project*

On behalf of the United States Environmental Protection Agency (EPA) and the United States Army Corps of Engineers (USACE), Kansas City District, CDM Federal Programs Corporation (CDM Smith) traveled to the River Mile (RM) 10.9 removal area on September 10 and 11, 2018 and provided field technical oversight for the annual visual inspection of the sediment cap. A visual inspection was attempted from shore on September 10, 2018, but was unsuccessful due to elevated water levels covering the cap. Poling was conducted by boat on September 11, 2018 along 12 transects across the cap at 10-foot intervals to confirm the presence of the armor layer below the overlying sediments and to measure the depth to these overlying soft sediments and the depth to armor layer from the water surface. Armor layer thicknesses were not assessed during the inspection.

Transects A through J were perpendicular to the shore with these ten transects intercepting the 2016 SPME sampler stations. The other two transects (X and Y) were located at the upstream and downstream ends of the cap, respectively, and were also perpendicular to the shore. Field activities were conducted by AECOM and Ocean Surveys, Inc. (OSI) on behalf of the Cooperating Parties Group (CPG).

The transects are presented in Figure 1 and are the same as the transects utilized during the 2017 inspection event. The poling points displayed in Figure 1 are from the August 2017 (not 2018) cap inspection and are provided for historical reference purposes only. GPS coordinates of the September 10-11, 2018 cap inspection poling points have not yet been received from the CPG as of the date of this memorandum. Photographs of field activities are presented in Attachment 1. A copy of the field logbook notes is provided in Attachment 2.

Summary of September 10, 2018 Field Activities

Personnel in Attendance

Yeqing Liu – CDM Smith
Andrew Bullard – CDM Smith (left approximately 15:40)
Diane Salkie – EPA (left approximately 16:25)
Rob Law – de maximis, inc. (left approximately 14:00)
Helen Jones – AECOM

AECOM indicated OSI was subcontracted to conduct the poling by boat and was using this day to set up survey equipment and survey benchmarks to prepare for the poling activities the following day. CDM Smith did not observe any OSI activities but AECOM noted OSI was setting up on their boat in Passaic River.

AECOM attempted to conduct a visual inspection of the cap from the shore at 13:45. However, the river water level was too high to observe the cap. The elevated water levels were likely due to heavy rains on this day. At 14:55, AECOM again attempted to conduct a visual inspection. The river water level had lowered noticeably but the cap still could not be observed. Visual inspections were again attempted at 16:02 and 16:40 but the cap was still not visible due to the elevated water levels caused by the rain on this day. Although low tide was not until 16:50, AECOM concluded the cap would not be exposed enough to conduct proper visual inspections due to the elevated water levels caused by the rain. AECOM stated that visual observations would be conducted by boat on the following day.

Summary of September 11, 2018 Field Activities

Personnel in Attendance

Yeqing Liu – CDM Smith

Helen Jones – AECOM

Ken Cadmus – OSI

Mike *surname unknown* – OSI

John Rolfe – de maximis, inc. (observed from shore)

AECOM provided instruction and direction as their subcontractor, OSI conducted the probing/poling from a motorized boat. At 08:25, OSI first steered the boat to the survey benchmark established the previous day at the Avondale Bridge (at approximately RM10.3) to check GPS calibrations and measure the water level. OSI then proceeded to probe/pole approximately four (4) to nine (9) points starting from the shore-side edge of the cap at all transects (A, B, C, D, E, F, G, H, I, J, Y, and X) in the morning while the tide was still high. OSI collected one measurement point every 10 feet along each transect, progressing towards the river channel from the shore. After the initial four to nine measurement points had been taken at each transect, OSI continued collecting measurements (10 feet apart along each transect) until at least two points were attempted outside of the channel-side edge of the cap based on the GPS location in relation to the as-constructed cap map. At least one of the two points at each transect was confirmed to be off-cap (i.e. probing/poling did not detect presence of armor layer or geotextile). A full set of measurement points was completed at each transect by boat¹. These measurements and associated notes are presented chronologically in Table 1.

Depth from the water surface to the top of overlying sediment was measured with a rigid plastic telescoping measuring pole with a flat disk-shaped bottom. The flat bottom allowed the measuring pole to rest on the sediment surface while the measurement was taken². If OSI detected sand (identified as a grainy texture and gritty sound upon poling) and was able to distinguish it as a separate layer from the overlying sediment, depth to sand was also recorded. Depth from the water surface to the top of the armor layer was measured with a long metal rod affixed with measuring tape. Depth to overlying sediment and depth to armor layer were recorded for each point unless the armor layer was not present. If the armor layer was not present, depth to geofabric layer was recorded instead. At off-cap

¹ During the last inspection event in August 2017, AECOM probed on land 36 points in 3 ft by 3 ft grids near the E and G transects to further investigate areas where significant variations in depth to or presence of armor layer was observed. AECOM then used this information to evaluate uncertainties in the probing/poling results (AECOM, December 2017). Since no probing/poling was conducted on land during the September 2018 event, OSI did not replicate this grid probing. Poling a 3 ft by 3 ft grid by boat would not have been able to generate the same accuracy as probing on land.

² AECOM had not been able to measure depth to the sediment surface by boat during the last inspection event in August 2017.

locations, only depth to overlying sediment was recorded. At each of the edge transects (X and Y), two or three off-cap and multiple on-cap locations were recorded to delineate the northern and southern edges of the cap.

At locations where the armor layer was not detected, additional points were taken immediately north, south, east, and west of the location to delineate the extent of the missing armor layer. Areas with missing armor layer included G-1 (approximately 5-foot diameter area of less dense armor), A-11 (approximately 5-foot diameter area of missing armor), near the edge of the cap at the B transect (spotty armor), and D-13 (at most 5-foot diameter area of missing armor).

The river currents and wind were noticeably less severe than the last inspection event in August 2017. Poling was completed at all transects by 15:25. OSI navigated the boat to the Avondale Bridge to recheck the GPS calibration and measure the water level again. No issues were noted with the calibration. At 16:34, OSI returned to RM10.9 for a visual inspection of the cap. AECOM recorded a 10-minute video of the cap and river starting from Transect X and ending at Transect Y from 16:52 to 17:02. AECOM also took photos of the cap at each transect between 17:02 and 17:30. These photos were captured close to low tide (17:40).

Depth to armor layer and depth to overlying sediment layer are summarized below:

Table 1: September 11, 2018 Cap Inspection Summary

| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|------|----------|----------|---|----------------------------------|--|--|--|
| 9:03 | A | A-1 | 48 | 13 | N/A | 61 | --- |
| 9:05 | A | A-2 | 52.8 | 12.2 | N/A | 65 | --- |
| 9:07 | A | A-3 | 64.8 | 6.2 | N/A | 71 | Location of former A-2 from Aug 2017 inspection |
| 9:18 | A | A-4 | 75.6 | 10.8 | 1.2 | 87.6 | --- |
| 9:20 | A | A-5 | 80.4 | 21.6 | N/A | 102 | Location of former A-3 from Aug 2017 inspection |
| 9:22 | A | A-6 | 86.4 | 30 | N/A | 116.4 | --- |
| 9:24 | A | A-7 | 94.8 | 42 | N/A | 136.8 | --- |
| 9:26 | A | A-8 | 105.6 | 44.4 | N/A | 150 | --- |
| 9:28 | A | A-9 | 115.2 | 40.8 | N/A | 156 | Within 4 ft of the former A-5 from Aug 2017 inspection |
| 9:31 | B | B-1 | 68.4 | 10.8 | N/A | 79.2 | --- |
| 9:33 | B | B-2 | 74.4 | 15.6 | N/A | 90 | Felt sand but could not measure |

| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|-------|----------|----------|---|----------------------------------|--|--|--|
| 9:36 | B | B-3 | 76.8 | 14.4 | N/A | 91.2 | Location of former B-2 from Aug 2017 inspection |
| 9:38 | B | B-4 | 86.4 | 14.4 | N/A | 100.8 | --- |
| 9:39 | B | B-5 | 91.2 | 16.8 | N/A | 108 | --- |
| 9:40 | B | B-6 | 96 | 33.6 | N/A | 129.6 | --- |
| 9:41 | B | B-7 | 102 | 19.2 | N/A | 121.2 | --- |
| 9:42 | B | B-8 | 108 | 28.8 | N/A | 136.8 | --- |
| 9:49 | C | C-1 | 44.4 | 6 | N/A | 50.4 | --- |
| 9:51 | C | C-2 | 60 | 8.4 | N/A | 68.4 | --- |
| 9:52 | C | C-3 | 66 | 13.2 | N/A | 79.2 | --- |
| 9:53 | C | C-4 | 68.4 | 10.8 | N/A | 79.2 | --- |
| 9:55 | C | C-5 | 72 | 14.4 | N/A | 86.4 | Close to former C-3 from Aug 2017 inspection |
| 9:56 | C | C-6 | 76.8 | 13.2 | N/A | 90 | Close to former C-4 from Aug 2017 inspection |
| 9:58 | C | C-7 | 80.4 | 25.2 | N/A | 105.6 | --- |
| 10:01 | C | C-8 | 85.2 | 30 | N/A | 115.2 | Within 5 ft of the former C-5 from Aug 2017 inspection |
| 10:03 | C | C-9 | 93.6 | 9.6 | N/A | 103.2 | --- |
| 10:07 | D | D-1 | 72 | 7.2 | N/A | 79.2 | Currently high tide |
| 10:09 | D | D-2 | 73.2 | 13.2 | N/A | 86.4 | --- |
| 10:10 | D | D-3 | 75.6 | 12 | N/A | 87.6 | --- |
| 10:12 | D | D-4 | 78 | 13.2 | N/A | 91.2 | Location of former D-3 from Aug 2017 inspection |
| 10:13 | D | D-5 | 81.6 | 16.8 | N/A | 98.4 | --- |
| 10:14 | D | D-6 | 85.2 | 27.6 | N/A | 112.8 | --- |
| 10:16 | D | D-7 | 88.8 | 27.6 | N/A | 116.4 | --- |
| 10:17 | D | D-8 | 94.8 | 24 | N/A | 118.8 | --- |
| 10:19 | D | D-9 | 102 | 31.2 | N/A | 133.2 | Within 6 ft of the former D-4 from Aug 2017 inspection |
| 10:22 | E | E-1 | 64.8 | 8.4 | N/A | 73.2 | --- |
| 10:25 | E | E-2 | 72 | 8.4 | N/A | 80.4 | --- |
| 10:27 | E | E-3 | 70.8 | 8.4 | N/A | 79.2 | --- |
| 10:28 | E | E-4 | 75.6 | 7.2 | N/A | 82.8 | Close to former E-2 from Aug 2017 inspection |
| 10:29 | E | E-5 | 76.8 | 10.8 | N/A | 87.6 | --- |

| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|-------|----------|----------|---|----------------------------------|--|--|---|
| 10:30 | E | E-6 | 78 | 13.2 | N/A | 91.2 | --- |
| 10:31 | E | E-7 | 84 | 10.8 | N/A | 94.8 | Close to former E-3 from Aug 2017 inspection |
| 10:33 | E | E-8 | 88.8 | 15.6 | N/A | 104.4 | --- |
| 10:34 | E | E-9 | 92.4 | 34.8 | N/A | 127.2 | --- |
| 10:37 | F | F-1 | 66 | --- | N/A | ND | Possibly off-cap location (start of transect). Close to former F-1 from Aug 2017 inspection. |
| 10:39 | F | F-2 | 68.4 | 7.2 | N/A | 75.6 | --- |
| 10:41 | F | F-3 | 72 | 10.8 | N/A | 82.8 | --- |
| 10:42 | F | F-4 | 74.4 | 12 | N/A | 86.4 | --- |
| 10:43 | F | F-5 | 75.6 | 14.4 | N/A | 90 | --- |
| 10:44 | F | F-6 | 78 | 16.8 | N/A | 94.8 | Close to former F-4 from Aug 2017 inspection where spotty armor was previously observed. OSI probed around this current location (F-6) to look for any areas of spotty armor but found the armor layer to be present in the surrounding area. |
| 10:47 | F | F-7 | 82.8 | 12 | N/A | 94.8 | --- |
| 10:49 | F | F-8 | 81.6 | --- | N/A | ND | No armor layer detected, geotextile fabric at 100.8 inches. Probing around the area revealed armor layer present at around 98.4 inches within 1 foot of the missing armor. |
| 10:51 | F | F-9 | 81.6 | --- | N/A | ND | No armor layer detected, geotextile fabric at 106.8 inches. Probing around the area revealed armor layer present at around 102 inches within 0.5 foot of the missing armor. |

| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|-------|----------|----------|---|----------------------------------|--|--|--|
| 10:57 | G | G-1 | 73.2 | 4.8 | N/A | 78 | Close to former G-1 from Aug 2017 inspection where spotty armor was previously observed. OSI probed around this current location to look for any areas of spotty armor and encountered missing armor (geotextile fabric at 81.6 inches) within a 5-foot area. OSI indicate the armor stones in this area were less dense and the metal poling rod was able to push between the armor stones. |
| 11:02 | G | G-2 | 79.2 | 10.8 | N/A | 90 | --- |
| 11:03 | G | G-3 | 84 | 14.4 | N/A | 98.4 | Close to former G-2 from Aug 2017 inspection |
| 11:12 | G | G-4 | 90 | 4.8 | N/A | 94.8 | --- |
| 11:13 | G | G-5 | 93.6 | 18 | N/A | 111.6 | --- |
| 11:14 | G | G-6 | 97.2 | --- | N/A | ND | No armor layer detected, geotextile fabric at 175.2 inches. Probing around the area revealed armor layer present at around 115.2 inches within 1 foot of the missing armor. OSI indicated the metal poling rod likely pushed between the armor stones at first measurement point. |
| 11:16 | G | G-7 | 96 | 22.8 | N/A | 118.8 | --- |
| 11:18 | G | G-8 | 100.8 | 20.4 | N/A | 121.2 | --- |
| 11:21 | H | H-1 | 57.6 | 1.2 | N/A | 58.8 | Close to former H-1 from Aug 2017 inspection |
| 11:23 | H | H-2 | 73.2 | 8.4 | N/A | 81.6 | --- |
| 11:24 | H | H-3 | 94.8 | 6 | N/A | 100.8 | Close to former H-2 from Aug 2017 inspection |
| 11:26 | H | H-4 | 105.6 | 12 | N/A | 117.6 | Close to former H-3 from Aug 2017 inspection |

| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|-------|----------|----------|---|----------------------------------|--|--|--|
| 11:28 | H | H-5 | 115.2 | 15.6 | N/A | 130.8 | --- |
| 11:30 | H | H-6 | 118.8 | 22.8 | N/A | 141.6 | Within 5 ft of the former H-4 from Aug 2017 inspection |
| 11:32 | H | H-7 | 121.2 | 24 | N/A | 145.2 | |
| 11:35 | I | I-1 | 88.8 | 8.4 | N/A | 97.2 | Close to former I-2 from Aug 2017 inspection |
| 11:36 | I | I-2 | 98.4 | 14.4 | N/A | 112.8 | Close to former I-1 and I-3 from Aug 2017 inspection |
| 11:38 | I | I-3 | 106.8 | 9.6 | N/A | 116.4 | --- |
| 11:39 | I | I-4 | 117.6 | 27.6 | N/A | 145.2 | --- |
| 11:40 | I | I-5 | 126 | 22.8 | N/A | 148.8 | --- |
| 12:04 | J | J-1 | 74.4 | 10.8 | N/A | 85.2 | Close to former J-1 from Aug 2017 inspection |
| 12:05 | J | J-2 | 92.4 | 21.6 | N/A | 114 | --- |
| 12:07 | J | J-3 | 111.6 | 28.8 | N/A | 140.4 | --- |
| 12:08 | J | J-4 | 130.8 | 25.2 | N/A | 156 | --- |
| 12:12 | Y | Y-1 | 99.6 | 6 | N/A | 105.6 | --- |
| 12:14 | Y | Y-2 | 145.2 | 20.4 | N/A | 165.6 | May have been depth to hardpan instead of armor. Difficult to tell poling from the boat. |
| 12:16 | Y | Y-3 | 154.8 | 12 | N/A | 166.8 | May have been depth to hardpan instead of armor. Difficult to tell poling from the boat. |
| 12:17 | Y | Y-4 | 152.4 | 25.2 | N/A | 177.6 | May have been depth to hardpan instead of armor. Difficult to tell poling from the boat. |
| 12:31 | X | X-1 | 40.8 | 9.6 | N/A | 50.4 | Close to former X-1 from Aug 2017 inspection |
| 12:32 | X | X-2 | 49.2 | 9.6 | N/A | 58.8 | Close to former X-2 from Aug 2017 inspection |
| 12:34 | X | X-3 | 52.8 | 20.4 | N/A | 73.2 | --- |
| 12:35 | X | X-4 | 64.8 | 14.4 | N/A | 79.2 | Within 5 ft of the former X-4 from Aug 2017 inspection |
| 12:37 | X | X-5 | 69.6 | 26.4 | N/A | 96 | --- |
| 12:38 | X | X-6 | 70.8 | --- | N/A | ND | No armor (off-cap) |

| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|-------|----------|----------|---|----------------------------------|--|--|---|
| 12:39 | X | X-7 | 74.4 | 42 | N/A | 116.4 | --- |
| 12:40 | X | X-8 | 78 | --- | N/A | ND | No armor (off-cap) |
| 12:41 | X | X-9 | 82.8 | 42 | N/A | 124.8 | --- |
| 12:47 | X | X-10 | 91.2 | 44.4 | N/A | 135.6 | --- |
| 12:48 | X | X-11 | 104.4 | --- | N/A | ND | No armor (off-cap) |
| 12:49 | X | X-12 | 105.6 | --- | N/A | ND | No armor (off-cap) |
| 12:51 | X | X-13 | 121.2 | 34.8 | N/A | 156 | --- |
| 12:53 | X | X-14 | 139.2 | 111.6 | N/A | 250.8 | Depth to armor layer measured with extension attached to metal poling rod. Was difficult to pole at this location and is possibly off-cap. |
| 13:01 | X | X-15 | 165.6 | --- | N/A | ND | Depth to sediment surface measured with a measuring tape attached to a weight plate because the telescoping measuring pole was too short. No armor (off-cap). |
| 13:06 | A | A-10 | 111.6 | 32.4 | N/A | 144 | --- |
| 13:07 | A | A-11 | 121.2 | --- | N/A | ND | No armor layer detected, geotextile fabric at 166.8 inches. Probing around the area revealed armor layer present at around 166.8 inches within 5 feet of the missing armor. |
| 13:10 | A | A-12 | 138 | 54 | N/A | 192 | --- |
| 13:13 | A | A-13 | 186 | --- | N/A | ND | No armor (off-cap) |
| 13:21 | B | B-9 | 91.2 | --- | N/A | ND | No armor layer detected, geotextile fabric at 132 inches. Probing around the area revealed armor layer missing within a 5-foot diameter circle around the B-9 location. |
| 13:23 | B | B-10 | 91.2 | 37.2 | N/A | 128.4 | --- |
| 13:24 | B | B-11 | 88.8 | 46.8 | N/A | 135.6 | --- |

| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|-------|----------|----------|---|----------------------------------|--|--|---|
| 13:25 | B | B-12 | 110.4 | --- | N/A | ND | No armor layer or geotextile fabric detected. However, this location is towards the channel-side edge of the cap. Close to former B-7 from Aug 2017 inspection. |
| 13:27 | B | B-13 | 121.2 | 27.6 | N/A | 148.8 | Follow-up location near B-12 (to investigate area of missing armor layer and geotextile) |
| 13:29 | B | B-14 | 132 | --- | N/A | ND | No armor (off-cap) |
| 13:32 | B | B-15 | 117.6 | --- | N/A | ND | Follow-up location near B-12. No armor layer detected, geotextile fabric at 144 inches. Probing around the area revealed armor layer present at around 135.6 inches nearby. OSI speculated that this area (around B-12) was a likely a transition area (more spotty areas of missing armor layer or cap) since it was close to the channel-side edge of the cap |
| 13:36 | C | C-10 | 62.4 | 28.8 | N/A | 91.2 | --- |
| 13:38 | C | C-11 | 70.8 | 36 | N/A | 106.8 | --- |
| 13:40 | C | C-12 | 79.2 | 34.8 | N/A | 114 | Within 5 ft of the former C-9 from Aug 2017 inspection |
| 13:41 | C | C-13 | 90 | 36 | N/A | 126 | --- |
| 13:43 | C | C-14 | 96 | 42 | N/A | 138 | Close to former C-7 from Aug 2017 inspection |
| 13:44 | C | C-15 | 104.4 | --- | N/A | ND | No armor layer detected, geotextile fabric at 146.4 inches. However, location was considered close enough to the channel-side edge of the cap to be potentially off-cap. |

| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|-------|----------|----------|---|----------------------------------|--|--|--|
| 13:46 | C | C-16 | 121.2 | --- | N/A | ND | No armor (off-cap) |
| 14:04 | D | D-10 | 67.2 | 37.2 | N/A | 104.4 | --- |
| 14:06 | D | D-11 | 74.4 | 31.2 | N/A | 105.6 | --- |
| 14:07 | D | D-12 | 85.2 | 33.6 | N/A | 118.8 | --- |
| 14:08 | D | D-13 | 92.4 | --- | N/A | ND | No armor layer detected, geotextile fabric at 132 inches. Close to former D-7 from Aug 2017 inspection. |
| 14:10 | D | D-14 | 94.8 | 31.2 | N/A | 126 | --- |
| 14:12 | D | D-15 | 106.8 | 26.4 | N/A | 133.2 | --- |
| 14:13 | D | D-16 | 115.2 | --- | N/A | ND | No armor (off-cap). Sandy, gravelly texture felt below the sediment layer but was not measurable. |
| 14:15 | D | D-17 | 120 | --- | N/A | ND | No armor (off-cap) |
| 14:17 | D | D-18 | 93.6 | 34.8 | N/A | 128.4 | Follow-up location near D-13 |
| 14:19 | D | D-19 | 90 | 18 | N/A | 108 | Follow-up location near D-13 |
| 14:21 | D | D-20 | 86.4 | 37.2 | N/A | 123.6 | Follow-up location near D-13. Further probing near D-13 was conducted to delineate the size of the missing armor area. About a 5-foot diameter circle of missing armor was determined to be located around D-13. |
| 14:26 | E | E-10 | 50.4 | --- | N/A | ND | No armor layer detected, geotextile fabric at 84 inches. Armor layer was felt right next to the metal poling rod at 73.2 inches. OSI speculated the poling rod likely hit between two armor stones. |
| 14:28 | E | E-11 | 55.2 | 28.8 | N/A | 84 | --- |
| 14:29 | E | E-12 | 63.6 | 48 | N/A | 111.6 | --- |
| 14:31 | E | E-13 | 70.8 | 38.4 | N/A | 109.2 | --- |


| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|-------|----------|----------|---|----------------------------------|--|--|---|
| 14:33 | E | E-14 | 82.8 | 38.4 | N/A | 121.2 | --- |
| 14:34 | E | E-15 | 105.6 | --- | N/A | ND | No armor (off-cap). Close to former E-6 from Aug 2017 inspection. |
| 14:36 | E | E-16 | 117.6 | --- | N/A | ND | No armor (off-cap) |
| 14:39 | F | F-10 | 32.4 | 20.4 | N/A | 52.8 | --- |
| 14:40 | F | F-11 | 34.8 | 28.8 | N/A | 63.6 | --- |
| 14:42 | F | F-12 | 38.4 | 38.4 | N/A | 76.8 | --- |
| 14:43 | F | F-13 | 46.8 | 39.6 | N/A | 86.4 | --- |
| 14:44 | F | F-14 | 56.4 | 30 | N/A | 86.4 | --- |
| 14:45 | F | F-15 | 66 | 33.6 | N/A | 99.6 | --- |
| 14:46 | F | F-16 | 80.4 | 32.4 | N/A | 112.8 | --- |
| 14:50 | F | F-17 | 92.4 | --- | N/A | ND | No armor (off-cap) |
| 14:51 | F | F-18 | 112.8 | --- | N/A | ND | No armor (off-cap) |
| 14:55 | G | G-9 | 49.2 | 32.4 | N/A | 81.6 | --- |
| 14:56 | G | G-10 | 55.2 | 38.4 | N/A | 93.6 | --- |
| 14:57 | G | G-11 | 63.6 | --- | N/A | ND | No armor (off-cap) |
| 14:58 | G | G-12 | 74.4 | --- | N/A | ND | No armor (off-cap) |
| 15:01 | H | H-8 | 68.4 | --- | N/A | ND | No armor layer detected, geotextile fabric at 117.6 inches. Since this location is off-cap (outside of the cap boundary according to GPS), no delineation was conducted |
| 15:02 | H | H-9 | 74.4 | --- | N/A | ND | No armor (off-cap) |
| 15:05 | I | I-6 | 84 | 21.6 | N/A | 105.6 | --- |
| 15:06 | I | I-7 | 91.2 | --- | N/A | ND | No armor (off-cap). |
| 15:09 | I | I-8 | 96 | --- | N/A | ND | Poling hit something hard at 152.4 inches. However, this location is off-cap (outside of the cap boundary according to GPS), thus it is likely not armor stone. |
| 15:13 | J | J-5 | 97.2 | 21.6 | N/A | 118.8 | --- |
| 15:14 | J | J-6 | 111.6 | --- | N/A | ND | No armor (off-cap) |

| Time | Transect | Location | Depth to Sediment from Water Surface (in) | Thickness of Sediment Layer (in) | Thickness of Sand Layer Underlying Sediment (in) | Depth to Armor Layer from Water Surface (in) | Comment |
|-------|----------|----------|---|----------------------------------|--|--|--------------------|
| 15:15 | J | J-7 | 118.8 | --- | N/A | ND | No armor (off-cap) |
| 15:18 | Y | Y-5 | 124.8 | 3.6 | N/A | 128.4 | --- |
| 15:20 | Y | Y-6 | 145.2 | 10.8 | N/A | 156 | --- |
| 15:21 | Y | Y-7 | 145.2 | 40.8 | N/A | 186 | --- |
| 15:23 | Y | Y-8 | 144 | --- | N/A | ND | No armor (off-cap) |

N/A – Not Available; indicates when OSI was unable to measure the sand layer as a distinct, separate layer from the overlying soft sediment.

ND – Not Detected; indicates the armor layer was not detected at the location.

Figure 1



Legend

- Poling Point/Armor Present
- Poling Point Off Cap
- Grid
- ◆ Porewater Station
- Transect
- Dredge/Cap Area
- No Dredge Area
- Hard Pan



0 50 100 200 Feet

Figure 1
Transect Poling Results, August 2017
Annual Cap Inspection

AECOM

Figure 1: Figure of poling/probing transects and sampler stations. Poling points displayed are from the August 21-22, 2017 cap inspection event. NOTE: An update to this figure with the poling points from the September 10-11, 2018 cap inspection will be created when the GPS coordinates of the September 2018 cap inspection are received from the CPG.

Attachment 1

Photographs of Field Activities



Photograph 1: Area of Transects G and H facing north (near low tide)

9/10/2018



Photograph 2: Area of Transect F facing north (near low tide)

9/10/2018



Photograph 3: Measuring depth to water surface from survey benchmark at Avondale Bridge

9/11/2018



Photograph 4: Measuring depth to sediment with telescoping measuring pole at D-1 location

9/11/2018



Photograph 5: Measuring depth to armor layer with long metal rod at D-1 location

9/11/2018



Photograph 6: Southern edge of cap around Transect X (facing northeast)

9/11/2018



Photograph 7: Approximate area of Transect A (facing northeast)

9/11/2018



Photograph 8: Approximate area of Transects C and D (facing east)

9/11/2018



Photograph 9: Approximate area of Transect F from utility corridor (facing northeast)

9/11/2018



Photograph 10: Area of Transect H and adjacent boat ramp (facing east)

9/11/2018



Photograph 11: Area of Transect I (facing southeast)

9/11/2018



Photograph 12: Area of Transect B with fallen tree branch (facing southeast)

9/11/2018



Photograph 13: Mudflats between Transects B and C (facing east)

9/11/2018

Attachment 2

Field Logbook Notes

50

Location Lyndhurst, NJ / Passaic Date 9/10/18
 Project / Client USEPA / USACE Passaic River RM10.9
 Cap Inspection / Bathymetric Survey YL 9/10/18

- 1210 Arrive at site. Met with Andrew Bullard (also CDM Smith)
- 1220 Leave for lunch to meet w/ Diane Salkire (EPA)
- 1335 Arrive back onsite, AECOM (Helen Jones) present. Also Rob Law of BEMAXIMUM. OSI is currently setting up survey equipment; haven't seen them yet.
- Weather: cloudy, light rain, 61°F
- 1345 Walked out to water's edge but water level is still too high, no cap camera layer visible.
- OSI is currently setting up survey bench mark near station 13.
- 1400 Returned back to cars to wait for tide to go down. YL 9/10/18
- 1410 Rob left around 1400.
- 1445 YL & A-B return from driving around the Passaic river to observe.
- 1455 Walked out to water again. Water has retreated some. OSI indicated via Helen Jones that storm surge had prevented river water level from going down as much as it was expected to.

51

Location Lyndhurst, NJ / Passaic Date 9/10/18
 Project / Client USEPA / USACE Passaic River RM10.9
 Cap Inspection

- 1542 Returned to parking lot to wait til tide further recedes.
- 1602 Headed back out onto water's edge (between hardpan & 0606 loc)
- 1615 Photo of 0607 & 0608 areas, facing North (Photo 1)
- 1625 Diane Salkire (EPA) leaves site. Andrew Bullard left around 1540. Helen Jones and I (YL) return back to parking lot.
- 1640 Return to water's edge (Photo 2)
- 1641 Photo of 0606 area, facing North. Helen notes this area is likely the most exposed of all the 10.9 RM shoreline. We will likely not see much more than this. More thorough visual observations are planned for the boat 8AM tomorrow.
- 1651 YL leaves site

YL 9/10/18

RL in the Rain

52 Location Lyndhurst, NJ / Passaic Date 9/11/18
 Project / Client USEPA / USACE Passaic RM 10.9
 Cap Inspection

805 YL arrived onsite. Helen Jones (AECM)
 Ken & Mike (OSI) are already present
 at site, setting up boat behind meadows.

YL 9/11/18 Gym at dock.
 Weather: cloudy & foggy, 61°F.
 expected to get up to almost 80°F
 later today.

820 H&S meeting stay clear of piling
 road and keep away from edges of
 boat. Leave water if thunderstorming.

825 Boat headed to survey benchmark
 to check calibration. Goal is to
 start at transects closest to shore
 while tide is higher. Helen indicates
 Jon Ralph is observing from the shore
 at the park.

845 Reached survey benchmark at Park
 Ave bridge around RM 9.5 for
 calibration (Photo 3). Will be measuring
 top of sediment (water depth) & top
 of armor at each location.

903 At transect A. Depth to ~~water~~ ^{sediment} 4 ft

Depth to armor 5' 5" ^{to armor} A-1

905 A-2 Depth to ~~water~~ ^{sediment} 4.4 ft, armor: 5' 5"

907 A-3 (old A-2 in 2017) 5.4 ft (to ~~water~~ ^{sediment}), 5' 11" ^{to armor}

53 Location Lyndhurst, NJ / Passaic Date 9/11/18
 Project / Client USEPA / USACE Passaic RM 10.9
 Cap Inspection

912 Fixing measuring tape on piling rd.
 Goal is to get a point measurement
 every 10 ft along a transect. Will
 finish 7 full transect first (A)
 and then do first 4 points of
 every remaining transect during high
 tide (in 1 hour).

918 A-4 (old A-3 in 2017) 6.3 ft to ~~water~~ ^{sediment}
 7.2 ft to sand, 7.3 ft to armor

920 A-5 6.7 ft to ~~water~~ ^{sediment} 8.5 ft to
 armor (old A-4 in 2017)

922 A-6 (not close to any old points)
 7.2 ft to ~~water~~ ^{sediment}, 9.7 ft to armor

924 A-7 7.9 ft to ~~water~~ ^{sediment}, 11.9 ft to
 armor

926 A-8, 8.8 ft to ~~water~~ ^{sediment}, 12.5 ft to
 armor

928 A-9, 9.6 ft to ~~water~~ ^{sediment}, 13 ft to armor
 (within 4 ft of old A-5)

931 B-1, 5.7 ft to ~~water~~ ^{sediment}, 6.6 ft to armor

933 B-2, 6.2 ft to ~~water~~ ^{sediment}, 7.5 ft to armor
 (felt sand)

936 B-3 (on old B-2), 6.4 ft to ~~water~~ ^{sediment}
 7.6 ft to armor

Rite in case Ken

54 Location Lyndhurst, NJ/Passaic Date 9/11/18
 Project / Client USEPA/USACE Passaic RM10.9
Cap Inspection

| | | | |
|------|-----|--------------------------------|---|
| 938 | B-4 | 7.2 ft | to sediment, 8.7 ft to armor |
| 939 | B-5 | 7.6 ft | to sediment, 9 ft to armor |
| 940 | B-6 | 8.0 ft | to sed, 10.8 ft to armor |
| 941 | B-7 | 8.5 ft | to sed, 10.1 ft to armor |
| 942 | B-8 | 9 ft | to sed, 11.4 ft to armor |
| 949 | C-1 | 3.7 ft | to sed, 4.2 ft to armor |
| 951 | C-2 | 5 ft | to sed, 5.7 ft to armor |
| 952 | C-3 | 5.5 ft | to sed, 6.6 ft to armor |
| 953 | C-4 | 5.7 ft | to sed, 6.6 ft to armor |
| 955 | C-5 | close to old C-3 | 6 ft to sed, 7.2 ft to armor |
| 956 | C-6 | close to old C-4 | 6.4 ft to sed, 7.5 ft to armor |
| 958 | C-7 | 6.7 ft | to sed, 8.5 ft to armor |
| 1001 | C-8 | close to old C-5, ~5 feet away | 7.1 ft to sed, 9.6 ft to armor |
| 1003 | C-9 | 7.8 ft | to sed, 8.6 ft to armor |
| 1007 | | currently at high tide | D-1 6 ft to sed, 6.6 ft to armor (photos 4 & 5) |
| 1009 | D-2 | 8.1 ft | to sed, 7.2 ft to armor |
| 1010 | D-3 | 6.3 ft | to sed, 7.3 ft to armor |
| 1012 | D-4 | old D-3 location in 2017 | |
| 1012 | D-5 | 6.5 ft | to sed, 7.6 ft to armor |
| 1013 | D-5 | 6.9 ft | to sed, 8.2 ft to armor |
| 1014 | D-6 | 7.1 ft | to sed, 9.4 ft to armor |

55 Location Lyndhurst, NJ/Passaic Date 9/11/18
 Project / Client USEPA/USACE Passaic RM10.9
Cap Inspection

| | | | |
|------|-----|------------------------|--|
| 1016 | D-7 | 7.4 ft | to sed, 9.7 ft to armor |
| 1017 | D-8 | 7.9 ft | to sed, 9.9 ft to armor |
| 1019 | D-9 | 8.5 ft | to sed, 11.1 ft to armor (6 ft to old D-4) |
| 1022 | E-1 | 5.4 ft | to sed, 6.1 ft to armor |
| 1025 | E-2 | 6 ft | to sed, 6.7 ft to armor |
| 1027 | E-3 | 5.9 ft | to sed, 6.6 ft to armor |
| 1028 | E-4 | near old E-2 from 2017 | 6.3 ft to sed, 6.9 ft to armor |
| 1029 | E-5 | 6.9 ft | to sed, 7.3 ft to armor |
| 1030 | E-6 | 6.5 ft | to sed, 7.6 ft to armor |
| 1031 | E-7 | near old E-3 from 2017 | 7 ft to sed, 7.9 ft to armor |
| 1033 | E-8 | 7.4 ft | to sed, 8.7 ft to armor |
| 1034 | E-9 | 7.7 ft | to sed, 10.6 ft to armor |
| 1037 | F-1 | near old F-1 5.5 ft | to sediments (no armor felt) 6.8 ft 9/11/18 likely off cap location, old F-2 |
| 1039 | F-2 | 5.7 ft | to sed, 6.3 ft to armor |
| 1041 | F-3 | 6 ft | to sed, 6.9 ft to armor |
| 1042 | F-4 | 6.2 ft | to sed, 7.2 ft to armor (near old F-3) |
| 1043 | F-5 | 6.3 ft | to sed, 7.5 ft to armor |

56

Location Lyndhurst, NJ Passaic Date 9/11/18
 Project / Client USEPA, USACE Passaic RM 10.9
 Cap Inspection

- 1044 F-6 (near old F-4 location - previously no armor detected) 6.5 ft to sediment, 7.9 ft to armor, 7.8 ft to armor (probe in the vicinity - armor seems present)
- 1047 F-7: 6.9 ft to sed, 7.9 ft to armor
- 1049 F-8 (~5 feet away from old F-5) 6.8 ft to sed, 8.1 ft to geotextile (no armor felt) ~9 foot away armor felt at ~8.2 ft to armor
- 1051 F-9: 6.8 ft to sed, 8.9 ft to geotextile ~0.5 ft away, felt armor ~8.5 ft
- 1057 G-1: 6.1 ft to sed, 6.5 ft to armor (really close to old G-2) - probing around G-1, geotextile at 6.5 ft
- ARM Rocks aren't very dense, getting in between the rocks with the probe ~5 ft area around G-1
- 1102 G-2: 6.6 ft to sed, 7.5 ft to armor
- 1103 G-3 (old G-2) 7.0 ft to sed, 8.2 ft to armor
- 1105 G-4: 7.5 ft to sed, 7.9 ft to armor
- 1112 G-5: 7.8 ft to sed, 9.3 ft to armor
- 1113 G-6: 8.1 ft to sed, 14.6 ft to geotextile 4.6 to armor less than (pushed between armor stored)
- 1114 4 foot away

57 Location Lyndhurst, NJ Passaic Date 9/11/18
 Project / Client USEPA, USACE Passaic RM 10.9
 Cap Inspection

- 1116 G-7: 8 ft to sediment, 9.9 ft to armor
- 1118 G-8: 8.4 ft to sediment, 10.1 ft to armor
- 1121 H-1: 9.8 ft to sediment, 4.9 ft to armor (old H-2 location)
- 1123 H-2: 6.1 ft to sediment, 6.8 ft to armor (old H-1) 9/11/18
- 1124 H-3 (old H-2): 7.9 ft to sediment 8.4 ft to armor
- 1126 H-4 (old H-3): 8.8 ft to sediment 9.8 ft to armor
- 1128 H-5: 9.6 ft to sediment, 10.9 ft to armor
- 1130 H-6 (~5 feet away from old H-4) 9.9 ft to sediment, 11.8 ft to armor
- 1132 H-7: 10.1 ft to sed, 12.1 ft to armor
- 1135 I-1: 7.4 ft to sed, 8.1 ft to armor (old I-2)
- 1136 I-2: 8.2 ft to sed, 9.4 ft to armor (close to old I-1 & I-3)
- 1138 I-3: 8.9 ft to sed, 9.7 ft to armor
- 1139 I-4: 9.8 ft to sed, 12.1 ft to armor

Ret in the Pan

58 Location Lyndhurst NJ Passaic Date 9/11/18
 Project / Client USEPA, USACE Passaic RM10.9
 CAP inspection

| | |
|------|---|
| 1140 | J-5: 10.5 ft to sed., 12.4 |
| 1145 | Bathroom break |
| 1201 | Heading back out to Transect J |
| 1204 | J-1 (close to old J1) 6.2 ft to sediment, 7.1 ft to armor |
| 1205 | J-2: 7.7 ft to sediment, 9.5 ft to armor |
| 1207 | J-3: 9.3 ft to sediment, 11.7 ft to armor |
| 1208 | J-4: 10.9 ft to sediment, 13.0 ft to armor |
| 1212 | J-1: 8.3 ft to sediment, 8.8 ft to armor |
| 1214 | J-2: 12.1 ft to sediment, 13.8 ft to armor |
| 1216 | J-3: 12.9 ft to sediment, 13.9 ft to armor close to shore for J-2 & J-3 (could also possibly be hard pan) |
| 1217 | J-4: 12.7 ft, 14.8 ft to armor or hardpan? (likely that J-2, J-3, & J-4 hit hardpan, not armor. Difficult to tell with the probe from the boat) |
| 1231 | X-1: 3.4 ft to sediment, 4.2 ft to armor (on former X-1) |
| 1232 | X-2: 4.1 ft to sediment, 4.9 ft to armor (on former X-2) |

59 Location Lyndhurst, NJ Passaic Date 9/11/18
 Project / Client USEPA, USACE Passaic RM10.9
 Cap Inspection

| | |
|------|---|
| 1234 | X-3: 9.4 ft to sediment, 6.1 ft to armor |
| 1235 | X-4: 5.9 ft to sediment, 6.6 ft to armor (~5 feet away from old X-4) |
| 1237 | X-5: 5.8 ft to sediment, 8 ft to armor |
| 1238 | X-6: 5.9 ft to sediment, no cap |
| 1239 | X-7: 6.2 ft to sediment, 9.7 ft to armor |
| 1240 | X-8: 6.5 ft to sediment, no cap |
| 1241 | X-9: 9.9 ft to sed, 10.4 ft to armor |
| 1247 | X-10: 7.6 ft to sed, 11.3 ft to armor |
| 1248 | X-11: 8.7 ft to sediment, no cap |
| 1249 | X-12: 8.8 ft to sediment, no cap |
| 1251 | X-13: 12.1 ft to sediment, 13 ft to armor |
| 1253 | X-14: 11.6 ft to sed, ran out of pole, attaching extension & redoing measurement YC 9/11/18, 20.9 ft to armor? possibly old cap here. |
| 1301 | X-15: 13.8 ft to sediment (switched to measuring tape + shore rather than w/ VIB cap) |

Rat in chicken

Location Lyndhurst, NJ Passaic Date 9/11/18
 Project / Client USEPA, USACE Passaic RM 10.9
Cap Inspection

- 1306 A-10.3 A to sed. next, 12 ft to armor
 1307 A-11: 10.1 ft to sediment, no armor, but ^{at 9.1 ft} geotextile (at 13.9 ft) felt about 5 feet away, armor observed at same depth (13.9 ft)
 1310 A-12: 11.5 ft to sediment 16 ft at armor layer
 1313 A-13: 15.5 ft to sediment, no cap
 1321 B-9: (from B-5) 7.6 ft to sediment Mat at 11 ft (~5 ft radius of no armor). Circulating around B-9 to find armor.
 1323 B-10: 7.6 ft to sediment, armor at 10.7 ft
 1324 B-11: 7.4 ft to sediment, armor at 11.3 ft (near B-12)
 1325 B-12 (former B-7) 9.2 ft to sediment, no armor, can't feel ^{geotextile} either (towards the edge of tank)
 1327 B-13: 10.1 ft to sediment, ^{at 12.4 ft} armor (near B-12)
 1329 B-14: 11 ft to sediment, no cap
 1332 B-15: 9.8 ft to sediment, ^{geotextile} mat at 12 ft (near B-12), nearby armor at 11.3 ft
 C seems to be a transition area near the water's edge of the cap

Location Lyndhurst, NJ Passaic Date 9/11/18
 Project / Client USEPA, USACE Passaic RM 10.9
Cap Inspection

- 1336 C-10: 5.2 ft to sediment, 7.6 ft to armor layer
 1338 C-11: 5.9 ft to sediment, 8.9 ft to armor layer
 1340 C-12: (5 feet from old C-9) 6.6 ft to sed, 9.5 ft to armor layer
 1341 C-13: 7.5 feet to sed, 10.5 ft to armor
 1343 C-14 (near old C-7): 8 ft to sed, 11.5 ft to armor (6 ft to armor)
 1344 C-15: 8.7 ft to sed, 12.2 ft to geotextile mat (no armor felt)
 1346 C-16: 10.1 ft to sed, no cap felt (off cap)
 1404 D-10: 5.6 ft to sed, armor at 8.7 ft
 1406 D-11: 6.2 ft to sed, 8.8 ft to armor
 1407 D-12: 7.1 ft to sed, 9.9 ft to armor
 1408 D-13 (at old D-7): 4.7 ft to sed, 11 ft to mat, ^{geotextile} no armor present
 1410 D-14: 7.9 ft to sed, armor at 10.5 ft
 1412 D-15: 8.4 ft to sed, 11.1 ft to armor
 1413 D-16: 9.6 ft to sed, no cap (sandy/gravelly filling)
 1415 D-17: 10 ft to sed, no cap
 1417 D-18: 7.8 ft to sed, 10.7 ft to armor (vicinity of D-13)

Notes in the Rain

62 Location Lyndhurst, NJ Passaic Date 9/11/18
 Project / Client USACE/USEPA Passaic RM10.9
 Cap Inspection

1419 D-19: 7.5 ft to sed, 9.0 ft to armor layer (vicinity of D-18)
 1421 D-20: 7.2 ft to sed, 10.3 ft to armor layer (vicinity of D-13)
 1422 Continued probing of D-13 vicinity to gauge size of missing armor area. About a 5 ft diameter of missing armor area at most
 1426 E-10: 4.2 ft to sed, gap: at 7 ft ^{scattered} armor right next to at 6.1 ft (poling reel likely hit between two armor pieces)
 1428 E-11: 4.6 ft to sed, armor layer at 7 ft
 1429 E-12: 5.3 ft to sed, armor at 9.3 ft
 1431 E-13: 5.9 ft to sed, armor at 9.1 ft
 1433 E-14: 6.9 ft to sed, armor at 10.1 ft
 1434 E-15: 8.8 ft to sed, armor at ^{vicinity is} no cap (close to former of E-6)
 1436 E-16: 9.8 ft to sed, no cap
 1437 F-10: 2.7 ft to sed, 4.4 ft to cap layer
 1440 F-11: 2.9 ft to sed, 5.3 ft to armor layer
 1442 F-12: 3.2 ft to sed, 6.4 ft to armor
 1443 F-13: 3.9 ft to sed, 7.2 ft to armor
 1444 F-14: 4.7 ft to sed, 7.2 ft to armor
 1445 F-15: 5.5 ft to sed, 8.3 ft to armor
 1446 F-16: 6.7 ft to sed, 9.4 ft to armor

63 Location Lyndhurst, NJ Passaic Date 9/11/18
 Project / Client USCPA/USACE Passaic RM10.9
 Cap Inspection

1450 F-17: 7.7 ft to sediment, no cap
 1451 F-18: 9.4 ft to sed, no cap
 1455 G-9: 4.1 ft to sediment, 6.8 ft to armor
 1456 G-10: 4.6 ft to sed, 7.8 ft to armor
 1457 G-11: 5.3 ft to sed, no cap ^{9/11/18}
 1458 G-12: 6.2 ft to sed, no cap
 1501 H-8: 5.7 ft to sed, ^{scattered} 9.8 ft outside the cap boundary - so not delineating
 1502 H-9: 6.2 ft to sed, no cap
 1505 I-6: 7 ft to sed, 8.8 ft to cap
 1506 I-7: 7.6 ft to sed, no cap
 1509 I-8: 8.0 ft to sed, 12.7 ft to ^{armor} ~~hard~~ ^{likely not cap (off cap location)}
 1513 J-5: 8.1 ft to sed, 9.9 ft to armor
 1514 J-6: 9.3 ft to sed, no cap
 1515 J-7: 9.9 ft to sed, no cap
 1518 Y-5 (old Y-1 location): 10.4 ft to sediment, 11.7 ft to armor layer
 1520 Y-6: 12.1 ft to sed, 13 ft to hardpan
 1521 Y-7: 12.1 ft to sed, 15.5 ft to hardpan
 1523 Y-8: 2 ft to sed, off cap
 Poling transects is completed. However low tide is not until 11:40. so visual


Plot in the Plan

64 Location Lyndhurst, NJ Passaic Date 9/11/18
 Project / Client USEPA/USACE Passaic RM 10.1
 Cap Inspection

observations cannot be completed yet
 1546 Headed back to Park Ave bridge
 for a navigation check / calibration
 1552 At park ave bridge to check nav.
 1634 Headed back to cap to do visual
 observations
 1650 Photo 6: southern edge of cap
 looking northeast (transect X)
 1652 Photo 7: approximate area of transect
 A)
 1653 Photo 8: transects C & D facing
 the shore (east)
 1654 Photo 9: transects F from utility
 corridor, facing northeast
 1658 Photo 10: area of transect H,
 facing east
 1702 Helen (AOC/DUI) finishes capturing
 the visual observation video of
 the cap
 1707 Photo 11: area of transect I (facing
 south east)
 1711 Photo 12: area of transect B (and
 tree fallen over (facing southeast)
 1718 Photo 13: Close up of mudflats
 between Transects B & C (facing east)

65 Location Lyndhurst, NJ Passaic Date 9/11/18
 Project / Client USEPA/USACE Passaic RM 10.1
 Cap Inspection

1747 Arrived back onshore
 1755 YL leaves site (OSI &
 Helen are still demobilizing -
 moving equipment from boat)



9/11/18
 YL

Plot on the River